ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0310	Chikkanna Lyt 4th Crs	Katte
Segment No.	**Total Length (m)**	
9/S-W0310/S020851	159.52	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	159.52	77.568860	13.074474	77.567414	13.074736	Katte Road	Govt Hospital

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Thindlu Colony, Kempegowdanagara and Surrounding areas in Ward No. 09, (Vidyaranyapura).	10000000	2020-21
Year	**Type of Work**	**Other Work Type**
2020 - 2021	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Drains by using solid block to rise the drain and providing covering slab	009-21-000001
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/153/2020-21	07/12/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/03/2022	02/03/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Muniraju B M		0.00
Phone No.	**E-Mail ID**	
9886778826		

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Field Inspection Details

mber of Trees	Any Other Information	Name
0		somadhekar g l

Date of Inspection 27/06/2022

Remarks

Category	Image	Photo Remark
Footpath Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	29/06/2022	27/07/2022	As proposed
SE	G R Devendra Naik	28/06/2022	27/07/2022	Forwarded
EE	Pradeep B N	27/06/2022	27/07/2022	Forward
AEE	Shivakumar M Goudar	27/06/2022	27/07/2022	Verified
AE	Somashekar G L	27/06/2022	27/07/2022	Mobile Verification Done
AE	Somashekar G L	27/06/2022	27/07/2022	Forward

Work executed Ashwath koote opp road from koote road to Govt hospital. this area comes under the Hindu colony

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0485	NA	Temple
Segment No.	**Total Length (m)**	
9/S-W0485/S020337	1130.75	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	1,130.75	77.566731	13.067797	77.570297	13.074430	GKVK Double Road	Govt Hospital

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Thindlu Colony, Kempegowdanagara and Surrounding areas in Ward No. 09, (Vidyaranyapura).	10000000	2020-21
Year	**Type of Work**	**Other Work Type**
2020 - 2021	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Drains by using solid block to rise the drain and providing covering slab	009-21-000001
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/153/2020-21	07/12/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/03/2022	02/03/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Muniraju B M		0.00
Phone No.	**E-Mail ID**	
9886778826		

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Field Inspection Details

Number of Trees	Any Other Information	Name
0		somadhekar g l

Date of Inspection 27/06/2022

Remarks

Category	Image	Photo Remark
Footpath Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	29/06/2022	27/07/2022	As proposed
SE	G R Devendra Naik	28/06/2022	27/07/2022	Forwarded
EE	Pradeep B N	27/06/2022	27/07/2022	Forward
AEE	Shivakumar M Goudar	27/06/2022	27/07/2022	Verified
AE	Somashekar G L	27/06/2022	27/07/2022	Mobile Verification Done
AE	Somashekar G L	27/06/2022	27/07/2022	Forward

The work executed from Gbark double road to Govt hospital. the area comes under the Hindlu colony

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0340	Mariyappa Lyt	Sathya Green Apartment
Segment No.	**Total Length (m)**	
9/S-W0340/S021115	454.45	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	454.45	77.571465	13.071586	77.567342	13.072216	Bullet Krishnappa Layout Cross Road	2nd Main Sir MV Layout

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Thindlu Colony, Kempegowdanagara and Surrounding areas in Ward No. 09, (Vidyaranyapura).	10000000	2020-21
Year	**Type of Work**	**Other Work Type**
2020 - 2021	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Drains by using solid block to rise the drain and providing covering slab	009-21-000001
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/153/2020-21	07/12/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/03/2022	02/03/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Muniraju B M		0.00
Phone No.	**E-Mail ID**	
9886778826		

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Field Inspection Details

Number of Trees	Any Other Information	Name
0		somadhekar g l

Date of Inspection	Remarks
27/06/2022	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	29/06/2022	27/07/2022	As proposed
SE	G R Devendra Naik	28/06/2022	27/07/2022	Forwarded
EE	Pradeep B N	27/06/2022	27/07/2022	Forward
AEE	Shivakumar M Goudar	27/06/2022	27/07/2022	Verified
AE	Somashekar G L	27/06/2022	27/07/2022	Mobile Verification Done
AE	Somashekar G L	27/06/2022	27/07/2022	Forward

2) The work executed S.T.M.V layout the area comes under from B.I.C layout cross road to 2nd main Thindlu colony

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike